| MJM ENVIRONMETNAL PTY LTD Site Visit Report | | | | | | |
|--|------------|-------------------------|-------|---------------|-----|--|
| Project Name: | | Tenterfield WTP | | Site Visit #: | 23 | |
| Contractor: | | Laurie Curran Water Pty | | Main System: | WTP | |
| | | Ltd | | Sub System: | - | |
| Date: | e: 30/09/2 | | Time: | 10.00am | | |
| Site Visit Objective/s: | | Progress update | | | | |
| Description of Works in Progress | | | | | | |
| Form work being installed for concrete wash water tank and chlorine contact tank | | | | | | |
| Filtrate balance tank installed | | | | | | |
| Chemical waste tank installed | | | | | | |
| Gantry in machine room has been installed | | | | | | |
| | | | | | | |
| Description of Planned Works | | | | | | |
| Concrete tanks being poured next Wednesday and Friday | | | | | | |
| Static test to be undertaken for 14 days on all tanks to ensure they hold water | | | | | | |
| Continue trenching and pipework for the PAC room | | | | | | |
| Items/Actions for TSC | | | | | | |
| • N/A | | | | | | |
| WHS Issues/Risks | | | | | | |
| N/A | | | | | | |
| Environmental Issues/Risks | | | | | | |
| N/A | N/A | | | | | |

Visual Record of Inspection









