MJM ENVIRONMETNAL PTY LTD Site Visit Report								
Project Name:		Tenterfield WTP		Site Visit #:	30			
Contractor:		Laurie Curran Water Pty Ltd		Main System:	WTP			
				Sub System:	-			
Date:	15/11/2	022 Time :		10.00am				
Site Visit Objective/s:		Progress update						

Description of Works in Progress

- Sam Shearer on-site today and tomorrow morning.
- Stainless-steel PAC tank lifted into position
- Concrete area for thickener and generator slab being marked out in preparation for concrete to be poured before Christmas
- MB Industries on-site today to go through the electrical components in the PAC area prior to concrete
- Darren Butler on-site + 4 other DTB Fabrications employees installing the purlins
- Edge protection installed around the Geobag area
- Bricklayer and his Niece continuing on with brick laying

Description of Planned Works

- Mobile scaffold being brought on-site for the bricklayer to reach the higher layers safely
- Earthworks to start in the generator and thickener area to give Darren Butler full access to the shed
- Planned to start earthworks for the raw water pipe next week
- First lot of stainless-steel pipes arriving in two weeks. Second lot two weeks after that.
- Install of electrical conduits in PAC area

Items/Actions for TSC

N/A

WHS Issues/Risks

- TSC Safety Officer on-site Monday 14^{th,} no major issues
- Did point out the brick layers plank and ladders weren't stamped or rated. Brick layer is no focusing on all lower sections until mobile scaffolding arrives on-site

Environmental Issues/Risks

Visual Record of Inspection























