

**MJM ENVIRONMETNAL PTY LTD****Site Visit Report**

<b>Project Name:</b>	Tenterfield WTP	<b>Site Visit #:</b>	36
<b>Contractor:</b>	Laurie Curran Water Pty Ltd	<b>Main System:</b>	WTP
		<b>Sub System:</b>	-
<b>Date:</b>	18/01/2022	<b>Time:</b>	1.00 pm
<b>Site Visit Objective/s:</b>	Progress update		

**Description of Works in Progress**

- Filter vessel being welded together
- Full electrical fit out of internal rooms
- Brick work continuing
- Framework being installed for chlorine and fluoride dosing rooms
- Excavation continuing for raw water line to the old WTP

**Description of Planned Works**

- Switchboard being brought on-site next week
- Continue electrical fit out
- Workers continuing to work on Australia Day public holiday

**Items/Actions for TSC**

- N/A

**WHS Issues/Risks**

- N/A

**Environmental Issues/Risks**

N/A

**Visual Record of Inspection**





























